





EH Message on Display

Not Applicable to 2G Model (CoolBot with cables on top and side)

1. A blinking EH on the CoolBot display means there is a problem with the Heater Cable (red tip).



2. Unplug the Heater Cable, clean the connector jack (tip) and replug your Heater Cable 2 times.



3. If the error clears we are good!
4. If the error persists discard the Heater and replace.

The CoolBot does not have a Workaround Mode for a bad Heater Cable (red tip).

DO NOT plug anything other than a replacement Heater Cable in the Heater port - it won't work!

To get a replacement Heater Cable under warranty (1 Year) please email support@storeitcold.com

To order a new Heater Cable please go to: <https://www.storeitcold.com/coolbot-accessories/>